



Grays Harbor County Satsop River Bridge

Truss Paint Condition











Grays Harbor County Satsop River Bridge


Typical Exposed Rebar in Approach Columns























Spokane County Old I-90 Over Spokane River



Elevation View

Spokane County Old I-90 Over Spokane River



Deck View

Spokane County Old I-90 Over Spokane River



Scouring Around Pier Bedrock



Spokane County Old I-90 Over Spokane River

Riverbed Material on Opposite Side of River

Spokane County Old I-90 Over Spokane River



View of Bridge with Respect to River

City of Tacoma Puyallup River Bridge



Elevation View

City of Tacoma Puyallup River Bridge



Deck View

City of Tacoma Puyallup River Bridge



Traffic Damage

City of Tacoma Puyallup River Bridge



Typical High Load Hit

City of Tacoma Puyallup River Bridge





Damaged Loose Deck Joint


City of Tacoma Puyallup River Bridge





Typical Under Deck Paint














Whakiakum County Grays River-Durrah Bridge



Elevation View

Whakiakum County Grays River-Durrah Bridge



Deck View

Whakiakum County Grays River-Durrah Bridge



Failing Paint

Whakiakum County Grays River-Durrah Bridge



Paint Condition

Whakiakum County Grays River-Durrah Bridge



Temporary Repair after Theft of Aluminum Rail

Whakiakum County Grays River-Durrah Bridge



Steel Girders